

ISO 80369-3 ENFIT design details create a dangerous misconnection

The photos below illustrate the dangerous misconnection.

NOTE: the ENFit female connector (shown below) is used on ENFit syringes and ENFit formula pump sets, such that formula can dangerously be pumped into a patient's airway.

Shiley adult tracheostomy tube with 15mm fitting-connector and female administration set supplied by GEDSA, shown not connected.



*Shiley adult tracheostomy tube with 15mm fitting-connector and female administration set supplied by GEDSA, **shown connected** in a wedge-lock fit, thereby compromising safety.*



NOTE:

The connector shown was supplied by GEDSA.

These photos shows a true misconnection fit between 80369-3 enteral female and tracheostomy tube cannula connector.



Showing a Shiley 15 mm tube cannula connector.



Showing a 80369-3 female connector misconnecting with a Shiley 15 mm tube cannula connector.

